

Quoted works for:

Customer: Colsterworth & District Parish Council

Inspection date: 17/10/2024

Site: Colster Way Play Area, Colster Way, Colsterworth, Lincolnshire, NG33 5JT

Inspector:

Wicksteed Leisure Ltd

Digby Street, Kettering

Northants NN16 8YJ

Tel: 01536 517028

Customerservices@wicksteed.co.uk

Item ID	Item	Manufacturer	Finding ID	Finding Details	Remedial Action	Risk Factor	Finding Photo	Item Photo	Qty	Code	Description	Unit Price	Total Price
941101	Litter Bin	Wicksteed Playgrounds	61736859	There are parts of the timber on the structure that have rotted	Replace all affected timbers	8	Yes	Yes	8	3722-226	Side Slat Cransley Bin	£86.52	£692.16
									32	2111-017	No.10 X 1 1/4" Round Head Woodscrew Bzp	£0.61	£19.52
941098	Cable Runway	Wicksteed Playgrounds	61736896	The chain links are worn excessively and require renewing	Replace worn chains	12	Yes	Yes	1	5082-330	Button Seat and Chain Assembly - cableway only	£257.00	£257.00
941098	Cable Runway	Wicksteed Playgrounds	61736899	The traveller bearings are worn	Replace the bearings	8	Yes	Yes	2	2903-026	Roller (for Cableway)	£73.21	£146.42
941098	Cable Runway	Wicksteed Playgrounds	61736898	The traveller brake isn't working	Repair / replace the brake	8	Yes	Yes	1	2903-027	Brake Spring (Cableway)	£81.19	£81.19
									2	2903-028	Brake Block (Cableway)	£19.97	£39.94
941124	Spring See-Saw	Wicksteed Playgrounds	61736888	There is/are bolt cap covers missing or damaged on the item	Replace missing or damaged bolt cap covers	4	Yes	Yes	8	3730-107	Fixing Cap	£1.67	£13.36
941111	Overhead Rotator	Wicksteed Playgrounds	61736902	There is/are bolt cap covers missing or damaged on the item	Replace missing or damaged bolt cap covers	4	Yes	Yes	8	2611-031_Cap	Black Poepplemann Cap	£0.60	£4.80
941111	Overhead Rotator	Wicksteed Playgrounds	61736901	There is some notable evidence of chain wear	Monitor for any further deterioration and replace when 40% worn	6	Yes	Yes	2	5082-332	Button Seat & Chain & Connection Housing - for hurricane swing only	£413.82	£827.64
									4	2215-515	M12 Washer Form G 36 Dia X 3Mm Thk	£1.20	£4.80
941102	1 Bay 2 Seat (Cradle)	Wicksteed Playgrounds	61736883	The item has missing component(s)	Consider replacing missing components	2	Yes	Yes	1	5901-204	Wicksteed Cradle Seat (Rubber Bbseat Curve Black)	£137.50	£137.50
									1	4061-212	A18 Straight Link Swing Chain for Cradle Seats	£88.00	£88.00
									2	4064-007	Small Shackle, Bolt & Pin	£10.65	£21.30
									2	2511-010	Ct10 Oilite Bush	£2.66	£5.32
											Labour cost carry out all work as detailed above		£600.00

Quoted works for:

Customer: Colsterworth & District Parish Council

Inspection date: 17/10/2024

Site: Colster Way Play Area, Colster Way, Colsterworth, Lincolnshire, NG33 5JT

Inspector:

Wicksteed Leisure Ltd

Digby Street, Kettering

Northants NN16 8YJ

Tel: 01536 517028

Customerservices@wicksteed.co.uk



Item ID	Item	Manufacturer	Finding ID	Finding Details	Remedial Action	Risk Factor	Finding Photo	Item Photo	Qty	Code	Description	Unit Price	Total Price	
Important notes														
Wicksteed have only quoted for the items shown above. There may be other areas that require attention so it is important that you fully read through the main Inspection Report and address all other findings as recommended.												Total cost, excluding carriage & VAT		£2,938.95

If your quotation includes for cutting back wet pour which is shrinking from the edges then please be aware that due to climatic change we are unable to offer any guarantees on the longevity of the infilling; this also applies to any infilling of gaps in rubber tiles. The shade of colour of any wet pour repairs may differ to existing.

The specification for any painting that is included is to rub down as necessary and for 1 coat of primer and 1 coat of gloss to be applied.

As inspections are visual non-dismantling inspections it is not always apparent until work commences on site that other parts may be required; if this is the case an additional quotation will be provided.

POA = Price on application

E&o.e.