

Quoted works for:

Customer: Colsterworth & District Parish Council

Inspection date: 17/10/2024

Site: Woolsthorpe By Colsterworth Play Area, Woolsthorpe Road, Woolsthorpe By Colsterworth, Lincolnshire, NG33 5NU

Inspector:

Wicksteed Leisure Ltd

Digby Street, Kettering

Northants NN16 8YJ

Tel: 01536 517028

Customerservices@wicksteed.co.uk

Item ID	Item	Manufacturer	Finding ID	Finding Details	Remedial Action	Risk Factor	Finding Photo	Item Photo	Qty	Code	Description	Unit Price	Total Price
941133	1 Bay 2 Seat (Cradle)	Wicksteed Playgrounds	61736944	There is some notable evidence of chain wear	Monitor for any further deterioration and replace when 40% worn	6	Yes	Yes	2	4061-211	Al6 Straight Link Swing Chain for Cradle Seats	£73.00	£146.00
									4	4064-007	Small Shackle, Bolt & Pin	£10.65	£42.60
									4	2511-010	Ct10 Oilite Bush	£2.66	£10.64
											Labour cost carry out all work as detailed above		£200.00
											Total cost, excluding carriage & VAT		£399.24

Important notes

Wicksteed have only quoted for the items shown above. There may be other areas that require attention so it is important that you fully read through the main Inspection Report and address all other findings as recommended.

If your quotation includes for cutting back wet pour which is shrinking from the edges then please be aware that due to climatic change we are unable to offer any guarantees on the longevity of the infilling; this also applies to any infilling of gaps in rubber tiles. The shade of colour of any wet pour repairs may differ to existing.

The specification for any painting that is included is to rub down as necessary and for 1 coat of primer and 1 coat of gloss to be applied.

As inspections are visual non-dismantling inspections it is not always apparent until work commences on site that other parts may be required; if this is the case an additional quotation will be provided.

POA = Price on application

E&o.e.