Quoted works for:

Customer: Colsterworth & District Parish Council

Inspection date: 17/10/2024

Site: Woolsthorpe By Colsterworth Play Area, Woolsthorpe Road, Woolsthorpe By Colsterworth, Lincolnshire, NG33 5NU

Wicksteed Leisure Ltd Digby Street, Kettering Northants NN16 8YJ Tel: 01536 517028



Customerservices@wicksteed.co.uk

Item ID	Item	Manufacturer	Finding ID Finding Details	Remedial Action	Risk Factor	Finding Photo	Item Photo	Qty	Code	Description	Illnit Price	Total Price
941133	1 Bay 2 Seat	Wicksteed	61736944 There is some notable evidence of chain	Monitor for any further	6	Yes	Yes	2	4061-211	Al6 Straight Link Swing Chain for	£73.00	£146.00
	(Cradle)	Playgrounds	wear	deterioration and replace						Cradle Seats		
				when 40% worn								
								4	4064-007	Small Shackle, Bolt & Pin	£10.65	£42.60
•								4	2511-010	Ct10 Oilite Bush	£2.66	£10.64
										Labour cost carry out all work as		£200.00
										detailed above		
Important notes												
Wicksteed have only quoted for the items shown above. There may be other areas that require attention so it is important that you fully read through the main Inspection Report and address all other findings										Total cost, excluding carriage &		£399.24
as recommen	ided.									VAT		

If your quotation includes for cutting back wet pour which is shrinking from the edges then please be aware that due to climatic change we are unable to offer any guarantees on the longevity of the infilling; this also applies to any infilling of gaps in rubber tiles. The shade of colour of any wet pour repairs may differ to existing.

The specification for any painting that is included is to rub down as necessary and for 1 coat of primer and 1 coat of gloss to be applied.

As inspections are visual non-dismantling inspections it is not always apparent until work commences on site that other parts may be required; if this is the case an additional quotation will be provided.

POA = Price on application

E&o.e.