Quoted works for:

Customer: Colsterworth & District Parish Council Inspection date: 02 October 2023 Site: Colster Way Play Area, Colsterworth NG33 5JT Inspector: Jim Hayes Wicksteed Leisure Ltd Digby Street, Kettering Northants NN16 8YJ

Tel: 01536 517028



Customerservices@wicksteed.co.uk

ltem ID	Item	Manufacturer	Finding ID Finding Details	Remedial Action	Risk Factor	Finding Photo	ltem Photo	Qty	Code	Description	Unit Price	Total Price
941102	1 Bay 2 Seat (Cradle)	Wicksteed Playgrounds	54110499 The chain links are worn in excess of 40 and require renewing	% Replace worn chains	8	<u>Yes</u>	<u>Yes</u>	2	4061-131	6' Anti-Wrap Chain For Single Tier Cradle Seat	£299.20	£598.40
	()	.,						4 4		Small Shackle, Bolt & Pin Ct10 Oilite Bush	£9.68 £2.42	
941098	Cable Runway	Wicksteed Playgrounds	54110472 The seat is less than 2.0 metres from the post when extended at 45 degrees at th end of the area of travel and does not meet the requirements of BS EN 1176 Part 4		8	<u>Yes</u>	<u>Yes</u>			Adjust position of the end stop		
941101	Litter Bin	Wicksteed Playgrounds	54110509 Wood rot at the timber slats.	Replace as required x 8	6	<u>Yes</u>	<u>Yes</u>	8	3722-226	Side Slat Cransley Bin	£78.65	£629.20
								32		No.10 X 1 1/4" Round Head Woodscrew Bzp	£0.55	£17.60
941111	Overhead Rotator	Wicksteed Playgrounds	54110516 The chain links are worn in excess of 40 and require renewing	% Replace worn chains	10	<u>Yes</u>	<u>Yes</u>	2		Button Seat & Chain & Connection Housing - for hurricane swing only	£376.20	£752.40
941118	See Saw	Wicksteed Playgrounds	54110492 Parts of the steel on this item have corroded excessively and the metal has perforated in places at the base of the main stanchion	Replace the main stanchion	10	<u>Yes</u>	<u>Yes</u>	1	5112-005	(A)Major Column Assy	£1,006.50	£1,006.50
								1		Wetpour Repair Kit - Top Layer - Black - 0.6 Sqm	£145.20	£145.20
941114	Skier	Wicksteed Playgrounds	54110480 The instruction label has faded	Replace the label	6	<u>Yes</u>	<u>Yes</u>	1	2910-007	Plaque for FLZ Skier c/w Rivets	£35.09	£35.09
941124	Spring See-Saw	Wicksteed Playgrounds	54110505 There are post / end caps missing from the item	Replace missing end cap x 1	6	<u>Yes</u>	<u>Yes</u>	1	3730-107	Fixing Cap	£1.52	£1.52
941112	Surfer	Wicksteed Playgrounds	54110478 There is/are bolt cap covers missing or damaged on the item	Replace missing or damaged bolt cap covers x 4	4	<u>Yes</u>	<u>Yes</u>	4	2611- 031_Cap	Black Poepplemann Cap	£0.54	£2.18

Quoted works for:

Customer: Colsterworth & District Parish Council Inspection date: 02 October 2023 Site: Colster Way Play Area, Colsterworth NG33 5JT Inspector: Jim Hayes Wicksteed Leisure Ltd Digby Street, Kettering Northants NN16 8YJ Tel: 01536 517028



Customerservices@wicksteed.co.uk

	Item ID Iten	n Manufacturer	Finding ID Finding Details	Remedial Action	Risk Factor	Finding Photo	ltem Photo	Qty	Code	Description	Unit Price	Total Price
[Important notes									Labour cost carry out all work as detailed above Hire of heras fencing for works to		£1,800.00 £357.00
	Wicksteed have only as recommended.	y quoted for the items shown above. There ma	ay be other areas that require attention so it is important	that you fully read through the main Inspection Report and	address all o	other findings				See Saw Total cost, excluding carriage & VAT		£5,036.49

If your quotation includes for cutting back wet pour which is shrinking from the edges then please be aware that due to climatic change we are unable to offer any guarantees on the longevity of the infilling; this also applies to any infilling of gaps in rubber tiles. The shade of colour of any wet pour repairs may differ to existing.

The specification for any painting that is included is to rub down as necessary and for 1 coat of primer and 1 coat of gloss to be applied.

As inspections are visual non-dismantling inspections it is not always apparent until work commences on site that other parts may be required; if this is the case an additional quotation will be provided.

POA = Price on application

E&o.e.