




# STONE DEFECTS (AS EXISTING)

**Key**


-  Deteriorated stone
-  New Ancaster stone (as replaced in 2010)




Side D  
(Northeast)



Side C (North)



Side B  
(Northwest)



Side A (West)



Side H  
(Southwest)




Side G (South)



Side F  
(Southeast)



Side E (East)



Rev A- Jul 2021: Updated for LBC/ tender

Suite S8, The Catalyst,  
University of York, East Campus  
Baird Lane, Heslington,  
York YO10 5GA

T: 01904 623034  
E: post@ppiy.co.uk



Do not scale off this drawing. If in doubt ask.  
Scale correct when drawing printed at A3

**Colsterworth War Memorial**  
Stone Investigation & Repairs  
Recording of stone defects

SCALE 1:20, 1:100  
DATE MAR 2021  
DRAWN EP

REV  
A

3501/103

All Drawings Copyright of PPIY Limited